


BAL HARBOUR

- V I L L A G E -

OFFICE OF THE VILLAGE MANAGER

LETTER TO COUNCIL

NO. 035-2019

To: Mayor Gabriel Groisman and Members of the Village Council
From: Jorge M. Gonzalez, Village Manager 
Date: March 1, 2019
Subject: **Collins Avenue/Harbour Way Traffic Signal Update**

The purpose of this Letter to Council (LTC) is to update you on the status of the traffic signal at the intersection located at Collins Avenue and Harbour Way East.

During the construction of the Oceana Condominiums, a traffic study was conducted regarding the redesign and traffic signal configuration of the intersection located at Collins Avenue and Harbour Way East. Upon completion of the study, the traffic signal design was changed to facilitate the flow of vehicular traffic at the Harbour Way intersection. The reconfiguration plans resulted in a signal change that prevented vehicles from making a legal U-turn at Harbour Way East.

Chief Flowers and his staff petitioned Florida Department of Transportation (FDOT) and Miami-Dade County Traffic Control to have the traffic signal at Harbour Way East reconfigured to the original traffic signalization, which included a legal U-turn prior to the construction of the Oceana.

On February 15, 2019, FDOT contractors and Miami-Dade County Traffic Control installed a 5-section signal head, and reconfigured the Harbour Way East traffic signal to the original settings. Motorist are now allowed to execute a legal U-turn from the Harbor Way East intersection. Attached are images of the intersection depicting the current and previous signage.

If you have any questions or need additional information, please feel free to contact Chief Raleigh Flowers at (305) 866-5000.



JMG/RI